



Inspection Detail

[Click to watch the video](#)



Client:	HDD Broker		
Inspected by:			
Location of Inspection:			
Phone No / Email:			
Date of Inspection:	3/2/2026	Job#:	
Year:	2022	Make:	DW
Model:	JT32AT	VIN/SN:	

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Inspection Details

Unit Information

Hours:	5,024	Date:	N/A
---------------	-------	--------------	-----

General Body

Paint condition:	See Notes	Panel dents:	No	Corrosion:	No
Dents/Bends:	No	Visible leaks:	No	Operator console pivot/lock:	No Damages Observed
Operator's Seat:	No Damages Observed	Operator Console Joysticks, switches, gauges:	No Damages Observed	Fresh water tank (if applicable):	N/A

Safety Equipment

Operator's presence switch (seat):	No Damages Observed	Safety switches:	No Damages Observed	Red safety bars (rod loader extensions):	N/A
Work lights:	No Damages Observed	Strike alert/ground wire:	No Damages Observed	Safety decals:	No Damages Observed

Breakout System

Breakout jaw wear:	No Damages Observed	Cylinder and hose condition:	No Damages Observed	Pins/bushings slop:	No Damages Observed
Front Stakedown System:	No Damages Observed	Auger condition:	No Damages Observed		

Main Drive System

Tracks (steel or rubber):	Rubber	Track condition:	See Notes	Sprockets/rollers:	No Damages Observed
----------------------------------	--------	-------------------------	-----------	---------------------------	---------------------

Rear Outriggers

Cylinder and hose condition:	No Damages Observed	Pins and bushings:	No Damages Observed	Bent/broken parts:	No
-------------------------------------	---------------------	---------------------------	---------------------	---------------------------	----

Carriage

Wear pads/carriage slop:	No Damages Observed	Motors and hoses condition:	No Damages Observed	Rack and pinion condition:	No Damages Observed
---------------------------------	---------------------	------------------------------------	---------------------	-----------------------------------	---------------------

Engine Details

Fluid level and condition:	N/A	Visible leaks:	No	Belts and pulleys:	No Damages Observed
Engine mounts:	No Damages Observed	Radiator/hoses:	No Damages Observed		

Operation

Engine start and idle:	No	Engine smoke:	No	Engine noises (tick/knock):	No
Rear outrigger operation:	No Damages Observed	Main rack tilt:	No Damages Observed	Front stakedown rotation/up/down:	No Damages Observed
Breakout vices open/close/rotate:	No Damages Observed	Rod loader lift/shuttle/alignment:	No Damages Observed	Carriage traverse (thrust/pullback):	No Damages Observed
Rotation motor fwd/reverse:	No Damages Observed	Mud pump on/off:	No Damages Observed		

Drill Rods

Rod count:	45	Bent rods:	No	Thread condition:	No Damages Observed
Corrosion:	No				

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tracks

Left Track Condition:	See Notes	Left Track Brand:	Obstructed	Left Track Size:	Obstructed
Left Track Tread Depth Measurement:	22/32"	Left Track Rollers:	No Damages Observed		
Right Track Condition:	See Notes	Right Track Brand:	Obstructed	Right Track Size:	Obstructed
Right Track Tread Depth Measurement:	32/32"	Right Track Rollers:	No Damages Observed		

Observations / Comments

The unit runs and operates.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Wear and Tear Items

Item Name	Item Comments
Rod Compartment Grab Iron	The iron grab on the left side of the rod compartment is slightly bent.
Right Track	The track has cuts, cracks, and gouges.
Left Track	The track is cracked and gouged.
Paint	The table of the rods, front auger frame, and side panels have damaged paint.
Hood	The hood panel is faded.
Hydraulic Lines	The hydraulic lines near the mast floor frame are rusty.
Armrest	The right armrest is stained and worn.
Front Windshield Wiper	The front wiper is not working. It is stuck and only performing a short movement.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.